

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

> JOHN R. BAZA Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Inspection Report

Permit Number:	C0070006		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, April 28, 2009		
Start Date/Time:	4/28/2009 2:00:00 PM		
End Date/Time:	4/28/2009 4:00:00 PM		
Last Inspection:	Monday, March 16, 2009		

Inspector: Steve Demczak, Environmental Scientist III Weather: Sunny, 60's, Small amount of snow cover

InspectionID Report Number: 1988

Accepted by: jhelfric 5/5/2009

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

	Total Permitted		
113.34	Total Disturbed		
113.34	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Types of Operations ✓ Underground ✓ Federal Surface ✓ State Loadout County **✓** Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issied.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Thursday, April 30, 2009

Inspector ID Number: 39

Permit Number: C0070006 *Inspection Type: PARTIAL

Inspection Date: Tuesday, April 28, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		~	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V		✓	
10.	Slides and Other Damage	V		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	~		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing		✓		
16.b	Roads: Drainage Controls		V		
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Tuesday, April 28, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The DOGM permit will expire on Jan. 28, 2012.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

Most of the diversions were opened and would function as designed. The other diversions did contain snow but the snow was melting and the water was pasting within the diversion.

4.c Hydrologic Balance: Other Sediment Control Measures

The disturb area is pocked to control sediment runoff.

8. Noncoal Waste

No non-coal waste was seen during the inspection.

9. Protection of Fish, Wildlife and Related Environmental Issues

Wildlife has been grazing the reclaim site.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

12. Backfilling And Grading

The disturb area was backfilled and graded. The permittee has received Phase II bond release.

13. Revegetation

The site was seeded.

18. Support Facilities, Utility Installations

There are no facilities.